Recalls Results by VIN - Vehicle Identification Number



VIN: 1D7HE42K15S244722

Year: 2005 Make: DODGE Model: DAKOTA CLUB CAB 4X2

Number of Open Recalls: 2

NHTSA Recall Number: 15V-313 Recall Date: May 29, 2015

Manufacturer Recall Number: R25

SUMMARY:

THE DRIVER AIRBAG INFLATOR HOUSING MAY RUPTURE, DUE TO EXCESSIVE INTERNAL PRESSURE, DURING NORMAL AIRBAG DEPLOYMENT EVENTS. THIS CONDITION IS MORE LIKELY TO OCCUR IF THE VEHICLE HAS BEEN EXPOSED TO HIGH LEVELS OF ABSOLUTE HUMIDITY FOR EXTENDED PERIODS OF TIME.

SAFETY RISK:

AN INFLATOR RUPTURE, DURING AIRBAG DEPLOYMENT EVENTS, COULD RESULT IN METAL FRAGMENTS STRIKING AND POTENTIALLY SERIOUSLY INJURING THE VEHICLE OCCUPANT(S).

REMEDY:

THE DRIVER AIRBAG INFLATOR MUST BE REPLACED.

RECALL STATUS: Recall INCOMPLETE

MANUFACTURER NOTES:

For more information, visit <u>recalls.mopar.com</u> or call 1-800-853-1403. Please have your VIN ready when calling.





If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an online complaint with NHTSA.

THIS RECALL DATA LAST REFRESHED: Oct 26, 2016

NHTSA Recall Number: <u>16V-352</u> Manufacturer Recall Number: S43 Recall Date: July 1, 2016

SIIMMARV.

THE FRONT PASSENGER AIRBAG INFLATOR HOUSING MAY RUPTURE WHILE DEPLOYING DURING A CRASH. THE POTENTIAL FOR SUCH RUPTURES MAY OCCUR IN SOME OF THE SUBJECT AIRBAG INFLATORS AFTER SEVERAL YEARS OF EXPOSURE TO PERSISTENT CONDITIONS OF HIGH ABSOLUTE HUMIDITY AND/OR HEAT AGING.

SAFETY RISK:

IN THE EVENT OF A FRONT PASSENGER AIRBAG INFLATOR RUPTURE, METAL FRAGMENT(S) COULD PASS THROUGH THE AIRBAG CUSHION MATERIAL, WHICH MAY RESULT IN ADDITIONAL INJURY OR DEATH TO VEHICLE OCCUPANTS.

REMEDY:

THE PASSENGER AIRBAG INFLATOR MUST BE REPLACED.

RECALL STATUS: Recall INCOMPLETE. Remedy not yet available

MANUFACTURER NOTES:

For more information, visit <u>recalls.mopar.com</u> or call 1-800-853-1403. Please have your VIN ready when calling.



If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an online complaint with NHTSA.

THIS RECALL DATA LAST REFRESHED: Oct 26, 2016

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the <u>Safety Issues section</u> and follow the instructions there.

Recall information for this manufacturer is only available going back to January 01, 1990. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.

Privacy - Terms

© Enter another VIN here: 1D7HE42K15S244722

I'm not a robot

Submit